




STANLEY



No. 4. Smooth



No. 5. Jack



No. 6. Fore

Stanley Bench Planes With Smooth Bottoms

Made from finest grey iron castings with sides and bottom machined smooth and true. Fully adjustable to satisfy all requirements—the opening of the mouth can be made wider or narrower as coarse or fine work may require, and the cutter can be adjusted for thickness and evenness of shaving. Handles and Knobs are made from rosewood.

Smooth Planes

| No. | | | Each |
|-----------------|----|--------------------------------------|--------|
| 2 | 7 | in. long, 1 $\frac{5}{8}$ in. Cutter | \$6.85 |
| 3 | 8 | in. long, 1 $\frac{3}{4}$ in. Cutter | 6.90 |
| 4 | 9 | in. long, 2 in. Cutter | 7.25 |
| 4 $\frac{1}{2}$ | 10 | in. long, 2 $\frac{3}{8}$ in. Cutter | 8.95 |

Jack Planes

No. 5 $\frac{1}{4}$ Plane is recommended especially for school shops.

Did you know that "Jack" Plane is short for "Jackass" Plane; an appropriate name for the Plane that is used for the hardest and roughest kind of work.

| No. | | | Each |
|-----------------|------------------|--------------------------------------|--------|
| 5 | 14 | in. long, 2 in. Cutter | \$8.25 |
| 5 $\frac{1}{4}$ | 11 $\frac{1}{2}$ | in. long, 1 $\frac{3}{4}$ in. Cutter | 7.55 |
| 5 $\frac{1}{2}$ | 15 | in. long, 2 $\frac{3}{8}$ in. Cutter | 11.15 |

Fore and Jointer Planes

| No. | | | Each |
|-----|----|--------------------------------------|---------|
| 6 | 18 | in. long, 2 $\frac{3}{8}$ in. Cutter | \$11.75 |
| 7 | 22 | in. long, 2 $\frac{3}{8}$ in. Cutter | 14.15 |
| 8 | 24 | in. long, 2 $\frac{5}{8}$ in. Cutter | 15.95 |

Construction Explained on
Opposite Page

